

<b>Machine Id</b>	<b>:- 1324</b>	<b>Serial No</b>	<b>:-</b>
<b>Category</b>	<b>:- Gear Related Machines</b>	<b>Model</b>	<b>:- LFS 1000</b>
<b>Country</b>	<b>:-</b>	<b>Make</b>	<b>:- Liebherr</b>
<b>Type of Machine</b>	<b>:- CNC Gear Shaping Machine</b>	<b>Year</b>	<b>:- 2006</b>
<b>Weight</b>	<b>:- 0.0</b>	<b>Dimensions</b>	<b>:-</b>
<b>Power</b>	<b>:-</b>	<b>Location</b>	<b>:-</b>

Specification :-

**GEAR SHAPING MACHINE –LIEBHERR LFS 1000**

**Yom : 2006**

**CNC : SIEMENS 840d**

**Modul from 0.5 to 12 mm**

**Column/head cutting angle : -1 / +12 °**

**Spindle attachment SK45**

**Spindle diameter : 120 mm**

**External cutting :**

**Maxi cutting diameter : 1000 mm**

**Maxi cutting height : 240 mm**

**Table diameter : 1000 mm**

**Table bore : 180 mm**

**Table speed : 121 tr/min**

**Cutter head position - stroke : 500 mm**

**Axis Z –stroke speed : 1800 mm/min**

**Cutter speed : de 50 à600 cps/min**

**Machine weight. 22 000 kg**